

Fig 1





Fig. 2



300 ~





Fig 4

400




420 →

590




59



VIEW A

490
↘
Fig6A



490
↘
Fig6B




Fig 7A





Fig 7B



VIEW A
SCALE 20:1






Fig 9



80





Fig 11



1040

1430

1460

1410

1420

5.

1470

1460

.0022
.0007

$\phi .0795$
 $\phi .0775$

$\phi .087$
 $\phi .085$

R .015
R .005

.055
.045

1440

1470

Fig 14A





Fig 14B

20T020" 60053001

Fig 15

1010



1070 ↗



SCALE 4:1

Fig 16A

1070 ↗




Fig 16B

Fig 18






Fig 19



[illegible]

Fig 22A

2030



2060




Fig 22B




Fig 23

2085




Fig 24

2015




Fig 26B




Fig 26A




Fig 26C





Fig 26D



2010E0"6905800T

Fig 26E 2620




Fig 26F




Fig 26G




Fig 27




Fig 28

200




Fig 30A

2810






Fig 30B



VIEW A
SCALE 2x

207050" 6505500T

Fig 31

3100





Fig 32




Fig 34






Fig 35A



F1935C

3600

3600

Fig 36B




Fig 36A

